

## BUILDING SAFETY CERTIFICATE

Referance : Your Letter No.

It is certified that the existing building **Amrutvahini International school at Ghulewadi Survey No 57/8/83, At Ghulewadi Tal.Sangamner Dist Ahmednagar** is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)
No. of Floor(s) in the Block	<b>CBSE School Main Building</b> a. Ground Floor Area- 1363.79 Sqm b. First Floor Area- 1246.19 Sqm c. Second Floor Area- 1269.98 Sqm	<b>Pre-Primary School</b> a. Ground Floor Area- 659.06 Sqm b. First Floor Area- 659.06 Sqm	-

The building is owned/occupied by **Amrutvahini sheti & shikshan vikas sanstha's Amrutvahini International school** have compiled with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Sub Divisional Engineer..... (Name of Department Govt.) on **03/02/2025** (date of inspection) in the presence of **Mrs Anil Baburao shinde At/Po Sangamner Tal.Sangamner Dist.A.Nagar** (CEO) and that the building/premises is fit for occupancy for running school with effect from **03/02/2025** for a period of..... **1 (one)** Years in accordance with rule and subject to compliance of the specific conditions as appended.

1.

2.

3.

4.

Issued on.....at.....by


Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with

Name:

Designation :

Name &amp; Address of Department/ Office:

  
Sub Divisional Engineer  
Public Works Sub Division  
Sangamner